K 021 SS=E

PAGE 25/30

PRINTED: 11/22/2010 FORM APPROVED

#### DEPARTMENT OF HEALTH AND HUMAN SERVICES OMB NO. 0938-0391 CENTERS FOR MEDICARE & MEDICAID SERVICES (X3) DATE SURVEY (X2) MULTIPLE CONSTRUCTION (X1) PROVIDER/SUPPLIER/CLIA STATEMENT OF DEFICIENCIES COMPLETED IDENTIFICATION NUMBER: AND PLAN OF CORRECTION 01 - MAIN BUILDING 01 A. BUILDING B. WING 10/25/2010 445135 STREET ADDRESS, CITY, STATE, ZIP CODE NAME OF PROVIDER OR SUPPLIER 220 LONGMIRE RD GOLDEN LIVINGCENTER - WINDWOOD CLINTON, TN 37716 (X5) COMPLETION DATE PROVIDER'S PLAN OF CORRECTION SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE (X4) ID PREFIX PREFIX REGULATORY OR LSC IDENTIFYING INFORMATION) TAG TAG DEFICIENCY) K 000 K 000 INITIAL COMMENTS 42 CFR 483.70(a) K3 BUILDING: 1-story Type V(111), unprotected, non-combustible construction with a complete automatic sprinkler system. K6 PLAN APPROVAL: 1978 K7 SURVEY UNDER: 2000 EXISTING K8 120-bed SNF/NF

Any door in an exit passageway, stairway enclosure, horizontal exit, smoke barrier or hazardous area enclosure is held open only by devices arranged to automatically close all such doors by zone or throughout the facility upon activation of:

NFPA 101 LIFE SAFETY CODE STANDARD

- a) the required manual fire alarm system;
- b) local smoke detectors designed to detect smoke passing through the opening or a required smoke detection system; and
- c) the automatic sprinkler system, if installed. 19.2.2.2.6, 7.2.1.8.2

This STANDARD is not met as evidenced by: Based on observation and interview, the facility failed to assure corridor fire doors closed to a positive latch.

The findings include:

Observation and interview with the Maintenance Director, on October 25, 2010 at 9:20 a.m. confirmed the corridor fire doors in the South 100

INBORATORY DIRECTOR'S OF PROVIDER'S PPLIER REPRESENTATIVE SIGNATURE

K021

K 021

Residents Affected No residents were affected.

Residents Potentially Affected All residents have the potential to be affected.

Measures/Systematic Changes Doors adjusted to allow them to close and latch properly.

Monitoring Changes Maintenance will monitor door closures daily during rounds and during fire drills making adjustments as needed. Any observed issues of noncompliance will be reported at monthly Safety Team Meeting X 3 months.

10/28/10

Any deficiency slatement/ending with an asterisk (\*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID: SEQ721

Facility ID: TN0108

If continuation sheet Page 1 of 5

PAGE 26/30

PRINTED: 11/22/2010 FORM APPROVED

(X5) COMPLETION

# DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

OMB NO. 0938-0391 (X3) DATE SURVEY (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION STATEMENT OF DEFICIENCIES COMPLETED IDENTIFICATION NUMBER: A. BUILDING 01 - MAIN BUILDING 01 B. WING 445135 10/25/2010

PREFIX

K 021

K 029

TAG

NAME OF PROVIDER OR SUPPLIER

AND PLAN OF CORRECTION

(X4) ID

PREFIX

TAG

### GOLDEN LIVINGCENTER - WINDWOOD

STREET ADDRESS, CITY, STATE, ZIP CODE 220 LONGMIRE RD

PROVIDER'S PLAN OF CORRECTION

(EACH CORRECTIVE ACTION SHOULD BE

CROSS-REFERENCED TO THE APPROPRIATE

DEFICIENCY)

CLINTON, TN 37716

K 021 Continued From page 1 hall, fire doors by room 122 and room 314 would not close to a positive latch. K 029 NFPA 101 LIFE SAFETY CODE STANDARD SS=E One hour fire rated construction (with 1/4 hour fire-rated doors) or an approved automatic fire extinguishing system in accordance with 8.4.1 and/or 19.3.5.4 protects hazardous areas. When the approved automatic fire extinguishing system option is used, the areas are separated from other spaces by smoke resisting partitions and doors. Doors are self-closing and non-rated or field-applied protective plates that do not exceed 48 inches from the bottom of the door are

SUMMARY STATEMENT OF DEFICIENCIES

(EACH DEFICIENCY MUST BE PRECEDED BY FULL

REGULATORY OR LSC IDENTIFYING INFORMATION)

This STANDARD is not met as evidenced by: NFPA 101, 8.3.6.1 (1). Pipes, conduits, bus ducts, cables, wires, air ducts, pneumatic tubes and ducts, and similar building service equipment that pass through floors and smoke barriers shall be protected by filling the space with a material that is capable of maintaining the smoke resistance of the smoke barrier or it shall be protected by an approved device that is designed for the specific purpose.

Based on observation and interview, the facility failed to assure fire rated walls and ceilings are maintained.

The findings include:

permitted. 19.3.2.1

Observation and interview with the Maintenance Director on October 25, 2010 at 10:40 a.m. confirmed unsealed penetrations in the rated ceiling of the 200 North mixing valve room, North electrical room above panel "Generator EM 3",

### K029

## Residents Affected

No residents were affected.

# Residents Potentially Affected

All residents have the potential to be affected.

## Measures/Systemic Changes

Penetrations in affected areas have been filled with material that is capable of maintaining the smoke resistance of the smoke barrier or maintaining fire rated barrier. Maintenance will inform affected contractors of requirements of maintaining these barriers. After contractors have been in attic or mechanical rooms, maintenance will ensure that they left no penetrations.

#### Monitoring Changes

Maintenance or designee will monitor for penetrations of smoke or fire rated barriers during weekly rounds and correct as needed. Any future reports of non-compliance will be reported to Safety Team Meeting X 3 months with action plan in place as needed.

11/12/10

DEPARTMENT OF HEALTH AND HUMAN SERVICES

HEALTH CARE FACILLITY

MAGE ZI/OW

PRINTED: 11/22/2010

FORM APPROVED OMB NO. 0938-0391

#### CENTERS FOR MEDICARE & MEDICAID SERVICES (X3) DATE SURVEY (X2) MULTIPLE CONSTRUCTION (X1) PROVIDER/SUPPLIER/CLIA STATEMENT OF DEFICIENCIES COMPLETED IDENTIFICATION NUMBER: AND PLAN OF CORRECTION 01 - MAIN BUILDING 01 DAIDING A B. WING 10/25/2010 445135 STREET ADDRESS, CITY, STATE, ZIP CODE NAME OF PROVIDER OR SUPPLIER 220 LONGMIRE RD GOLDEN LIVINGCENTER - WINDWOOD CLINTON, TN 37718 PROVIDER'S PLAN OF CORRECTION (X5) COMPLETION DATE (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE SUMMARY STATEMENT OF DEFICIENCIES (X4) ID PREFIX PREFIX (EACH DEFICIENCY MUST BE PRECEDED BY FULL TAG REGULATORY OR LSC IDENTIFYING INFORMATION) TAG DEFICIENCY) K 029 Continued From page 2 K 029 Kitchen gas supply pipe for the cooking equipment, and insulated water pipe behind the K045 riser and above the second hot water heater in the housekeeping supply room. Residents Affected NFPA 101 LIFE SAFETY CODE STANDARD K 045 K 045 No residents were affected. SS=D Illumination of means of egress, including exit Residents Potentially Affected discharge, is arranged so that failure of any single All residents have the potential to be lighting fixture (bulb) will not leave the area in affected. darkness. (This does not refer to emergency lighting in accordance with section 7.8.) 19.2.8 Measures/Systemic Changes All exit doors were immediately checked for adequate lighting. Licensed electrician installed fixtures as indicated. This STANDARD is not met as evidenced by: Based on observation and interview, the facility Monitoring Changes failed to assure outside exits were illuminated Maintenance will observe for with multiple bulbs or fixtures. adequate working lighting during The findings include: daily rounds. Any issues will be Observation and interview with the Maintenance Director, on on October 25, 2010 at 10:40 a.m. corrected immediately and reported confirmed the outside lights at the exits from the to monthly Safety Team meeting X 3 months. south 300 hall exit was burnt out and the south exits by 200 and 212 had single bulb light fixtures. K 062 | NFPA 101 LIFE SAFETY CODE STANDARD K 062 11/19/10 SS=E Required automatic sprinkler systems are continuously maintained in reliable operating condition and are inspected and tested periodically. 19.7.6, 4.6.12, NFPA 13, NFPA K062 25, 9,7,5 Residents Affected No residents were affected. This STANDARD is not met as evidenced by: Based on observation and interview, the facility Residents Potentially Affected All residents have the potential to be failed to assure the sprinkler system piping was not used to support non-system components. affected.

DEPARTMENT OF HEALTH AND HUMAN SERVICES

PAGE 28730

PRINTED: 11/22/2010 FORM APPROVED OMB NO. 0938-0391

CENTERS FOR MEDICARE & MEDICAID SERVICES (X3) DATE SURVEY (XZ) MULTIPLE CONSTRUCTION (X1) PROVIDER/SUPPLIER/CLIA STATEMENT OF DEFICIENCIES COMPLETED IDENTIFICATION NUMBER: AND PLAN OF CORRECTION A. BUILDING 01 - MAIN BUILDING 01 B. WING 10/25/2010 445135 STREET ADDRESS, CITY, STATE, ZIP CODE NAME OF PROVIDER OR SUPPLIER 220 LONGMIRE RD GOLDEN LIVINGCENTER - WINDWOOD CLINTON, TN 37716 PROVIDER'S PLAN OF CORRECTION (XS) SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL PREFIX (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE PREMIX REGULATORY OR LSC IDENTIFYING INFORMATION) TAG DEFICIENCY) TAG Measures/Systemic Changes K 062 K 062 Continued From page 3 Maintenance removed low voltage (NFPA 13, '9-1.1.7) wiring from sprinkler pipes through The findings include: out building. Maintenance will inform Observation and interview with the Maintenance 11/12/10 affected contractors not to attach wiring Director, in the attic above North 200 hall, on to sprinkler pipes. After contractors have October 25, 2010 at 12:40 p.m. confirmed been in these areas, maintenance will electrical wiring and phone lines in the attic was ensure compliance. attached to the main sprinkler line. Monitoring Changes K 073 K 073 NFPA 101 LIFE SAFETY CODE STANDARD Maintenance will monitor compliance SS=F during weekly rounds. Any issues will No furnishings or decorations of highly flammable be corrected immediately and reported character are used, 19.7.5.2, 19.7.5.3, 19.7.5.4 to monthly Safety Team meeting X 3 months. K073 This STANDARD is not met as evidenced by: Residents Affected Based on staff interviews, the facility failed to No residents were affected. assure combustible decorations were fire Residents Potentially Affected retardant (NFPA 110, 19.7.5.4). All residents have the potential to be The findings include: affected. Interview with the Maintenance Director and Measures/Systemic Changes Housekeeping Supervisor, on October 25, 2010 All combustible decorations in at 10:50 a.m., confirmed the facility falled to treat common areas and corridors holiday decorations with a fire retardant and could were treated with fire retardant not provide documentation that decorations in the corridors and common areas were treated with and tagged and logged when treated. fire retardant material. Maintenance will maintain log K 147 and periodically re-treat decorations NFPA 101 LIFE SAFETY CODE STANDARD K 147 per fire retardant manufacturer's SS=E Electrical wiring and equipment is in accordance specifications. Staff have been with NFPA 70, National Electrical Code. 9.1.2 educated to have maintenance treat decorations used in corridors. Monitoring Changes Maintenance will observe for This STANDARD is not met as evidenced by: untreated decorations during Based on observation and interview, the facility daily rounds. Any issues will failed to assure extension cords and multiple be corrected immediately and 11/09/10 outlet adapters were not used (NFPA 99. reported to monthly Safety Team 3-3.2.1.2 (d) (2) states: There shall be sufficient Meeting X 3 months. receptacles located so as to avoid the need for

HEALTH CARE FACILITY

DEPARTMENT OF HEALTH AND HUMAN SERVICES OMB NO. 0938-0391 CENTERS FOR MEDICARE & MEDICAID SERVICES (X3) DATE SURVEY COMPLETED (X2) MULTIPLE CONSTRUCTION (X1) PROVIDER/SUPPLIER/CLIA STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION DENTIFICATION NUMBER: 01 - MAIN BUILDING 01 A. BUILDING 10/25/2010 B. WING 445135 STREET ADDRESS, CITY, STATE, ZIP CODE NAME OF PROVIDER OR SUPPLIER 220 LONGMIRE RD GOLDEN LIVINGCENTER - WINDWOOD CLINTON, TN 37716 (XS) COMPLETION DATE PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE SUMMARY STATEMENT OF DEFICIENCIES (SACH DEFICIENCY MUST BE PRECEDED BY FULL PREFIX PREFIX TAG REGULATORY OR LSC IDENTIFYING INFORMATION) DEFICIENCY) TAG K 147 K 147 Continued From page 4 K147 extension cords or multiple outlet adapters.) The findings include: Residents Affected Observation and interview with the Maintenance No residents were affected. Director, on October 25, 2010 between 1:00 p.m. and 2:10 p.m. confirmed resident room 214 and Residents Potentially Affected 218 was observed with a power strip next to the All residents have the potential to be resident bed with medical devices plugged into it. affected. Measures/Systemic Changes Identified power strips were immediately removed and the medical devices were plugged into wall outlets. All resident rooms were immediately checked for any medical devices plugged into power strips. Staff have been educated regarding appropriate usage of power strips and to correct any issues of noncompliance immediately. Monitoring Changes Maintenance will observe for use of power strips used to provide power for medical devices during daily rounds targeting random rooms. Any issues will be corrected immediately and reported to monthly Safety Team Meeting X 3 months. 11/11/10

PRINTED: 11/22/2010 FORM APPROVED